

Bug or feature?

Posted by KevinC - 25 Feb 2014 20:29

When I have UID's turned on I no longer have the PT0/1/25 indication. It only shows NFM.

=====

Re: Bug or feature?

Posted by teknishun - 08 Mar 2014 06:40

KevinC wrote:

When I have UID's turned on I no longer have the PT0/1/25 indication. It only shows NFM.

Try it again with the latest firmware release. I have my 536HP running that way right now and it is displaying everything just fine. But I have also changed NFM to FM for better audio clarity.

teknishun KF5OPQ

=====

Re: Bug or feature?

Posted by KevinC - 08 Mar 2014 20:55

teknishun wrote:

KevinC wrote:

When I have UID's turned on I no longer have the PT0/1/25 indication. It only shows NFM.

Try it again with the latest firmware release. I have my 536HP running that way right now and it is displaying everything just fine. But I have also changed NFM to FM for better audio clarity.

teknishun KF5OPQ

Yes, the update corrected the issue.

=====