

Garbled transmission/reception

Posted by Santacarl - 11 Oct 2018 00:24

Hello All,

I am having a problem with a frequency I've monitored for several years. Recently something seems to have changed and now reception (this freq only) are garbled/distorted.

I use Sentinel and the Freq and settings there haven't changed since I first began using them. I verified this with another person on their scanner and they too receive the transmissions in a garbled/distorted way. You can make out most of the words but some are so garbled that they are unintelligible....almost like another freq is bleeding over to cause some kind of strange modulation but you don't hear any others than the assigned users transmitting...

Does anyone have any idea on what slight change in the transmitter setup could cause this? Something like a switch of the DCS number is now slightly different (as an example)....?

Any thought would be appreciated....

=====

Re: Garbled transmission/reception

Posted by Santacarl - 03 Jun 2020 19:39

Well, I figured it out....

Full Time Voice Inversion.

I don't guess there's a way to un-invert on the BCD436HP...

=====